VALUE IN COLUCT IN TOUT TO	Work	Order	ID 1	108448
----------------------------	------	-------	------	--------

108448

Page 1

October 17-13 1	:31:09 PM												
	D4003-5			Accept	7	N900	040	100)* s	etup Star	1.71	S1*	
Item Name:	Fuel Pick Up Line									Stop	*N	S2*	
Start Date:	10/17/13 Start Qt	y: 2.00	*2*			Cust Item I	D:						
Required Date:	10/17/13 Req'd Q	ty: 2.00	*2*			Customer:							
Reference:			-										
Approvals:	Process Plan: ML	.5	Date: \\3-\0-7	∠\ Tooling:	,	Da	ite:		R	tun Star	1/1	R1*	
	QC:		Date:	SPC (Y/	N):	Da	ıte:			Stop	*N	R2*	
Sequence ID/ Work Center ID	Operatio Descripti			Set U Run l	p/ Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Revision Nbr												
D4003	A												
100				0.00									
100 Doosan		Мето		0.00	OAS 40 9-89	13/11/02	_						
- Doosan Lathe		1- Cut tube as FA911	per dwg		68-6	5,,					~		
· ·		FOLIO REV:_ DWG REV:_	AA A										
		DEBURR											
110	QC2- Inspe	ect parts off mad	chine FAI/FAIB	0.00	(OAS)	13/11/0	12.						
110					* 4.O	15/11/0			2				
QC		Memo		0.00									
Quality Control			•										

DQA:		Date:	
------	--	-------	--

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

								•		QA Closed:	Date	:
Work Orde	r·				DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
Part N NCR N	0.				Rework Scrap Use-as-is Work Order Update] 	۱ herm	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite	-	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root	1	T		Descri	ption of work order update	Init	tial	Ac	tion	Sign &		
Cause	Date	Step	Qty		or Non-conformance	Chief			ription	Date	Verification	QC Inspector
Doc/Data							6					
quip/Tooling												
Operator												
Material						1						
Setup												
Other												
rocess	╗				•							
Supplier		1										
Training												
Jnapproved						1.						
					F	AULT (CATE	GORY	•	•		
Landin	ng Gear				General					_		
	Bending				Bend	G	rain			Ovalized		Pressure/Forced
	Centre N	ot Conce	ntric to	o/s	BOM/Route	На	ardwa	re		Over/Under	tolerance	Temperature/Cure
	Cracks				Broken/Damaged	In:	specti	on Incomplete		Part Incorred	ct	Weld
<u> </u>	Crushed/	'Crimped			Burrs	ln	struct	ions Incomplete/	'Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled
	Cuffs				Contamination	Шм	lainte	nance		Part Moved		
	Heat Trea	at			Countersink	М	islabe	led		Positioned W	Vrong	
	Inspectio	n Strip in	Tube		Cut Too Short	Шм	isread	1		Power Loss/	Surge	Other
	Ripples in	n Bend		<u> </u>	Drill Holes	Що	ffset					
	Torque V	Vaves in (Extrusio	n L	Drawing		ut of C	Calibration				
ļ	Turning S	Sequence			Finish		ut of S	equence				
	Wave/Tv	vist in Tul	be		Folio		utside	Dimensions				

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work	Ord	er ID	108448
October-	17_13	1.31.00	PM

Page 2

Item ID: D4003-5 Accept *N900040100* Setup Start **Revision ID:** Stop Item Name: Fuel Pick Up Line **Start Date:** 10/17/13 Start Oty: 2.00 **Cust Item ID:** Req'd Qty: 2.00 Required Date: 10/17/13 **Customer:** Reference: Run Process Plan: Date: _____ Tooling: Approvals: Date: Stop Date: SPC (Y/N): Date: Tool ID Sequence ID/ Operation Set Up/ Tool # Plan Accept Reject Reject Insp. Qty Number Stamp Work Center ID Description **Run Hours** Code Qty OAC 120 QC8- Inspect parts - second check 0.00 *120* 0.00 OC Memo Quality Control Identify as per dwg & Stock Location: WH, 203 170 *170* 0.00 Packaging Memo Packaging 18-11-06 pl/3-11-04 QC21- Final Inspection - Work Order Release 0.00 180 *120* QC 0.00 Memo Quality Control

NCR:	Yes	/ No				WORK ORDER NON-	COI	NFORM	MANCE / UPDATE					
											QA Closed:	Da	ite:	
Work Orde	er: _					DISPOSITION	7				PARTMENT			
Part I	-					Rework Scrap Use-as-is		Therm	Skid-tube Crosstube Wachining Small Fab noforming Finishing		-1	Water Jet d. Eng. Coor re/Packaging		Engineering Quality Other
NCR i	NO.					Work Order Update	J		Large Fab Composite	<u>-</u> L_	J	Supplier	<u>L</u>	
Root Cause		Date	Step	Qty		ption of work order update or Non-conformance		Initial nief Eng	Action Description		Sign & Date	Verificatio	n	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved						,								
Landi	ing G	iear				r General	AUI	LT CATE	JUNT					
Landi		Bending Centre N Cracks Crushed/ Cuffs Heat Tre- Inspectic Ripples in	'Crimped at on Strip in		D/S	Bend BOM/Route Broken/Damaged Burrs Contamination Countersink Cut Too Short Drill Holes		┥ :	on Incomplete ions Incomplete/Unclear enance eled		Ovalized Over/Under Part Incorre Part Lost/M Part Moved Positioned V	ct issing Vrong		Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled Other
1		Torque V	Vaves in I	Evtrucion	, F	Drawing		Out of C	Calibration					

Out of Sequence

Outside Dimensions

DQA:

Date:

Turning Sequence

Wave/Twist in Tube

Finish

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Page 1

Work Order ID:

108448

Parent Item:

D4003-5

Parent Item Name:

Fuel Pick Up Line

Start Date: 10/17/13

Required Date: 10/17/13

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP rev A 10.01.11 new issue Prelim EC verified by:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6T0.500W.035 6061-T6 RD Tube .500 x.0)35W	Purchased	No			100	f	92.0300	3	6.3157894	(40)	12	/11/02
				Location		Loc Qty	Lo	c Code			. 9− 89		
				MAT014		92.03							
				7	21848	65.68	1			6,0			
				4	1692	26.35							

											DQA:	Da	ate: _	
NCR:	/es	/ No				WORK ORDER NON-C	CONF	ORN	MANCE / UPDATE					
-			÷			T					QA Closed:	Da	ate:	
Work Orde	or.					DISPOSITION			AGAINST	DE	DEPARTMENT/PROCESS			
Part N						Rework Skid-tube Crosstube Machining Small Fab Thermoforming Finishing Work Order Update Large Fab Composite				Water Jet Prod. Eng. Coor. Rec/Store/Packaging Supplier			Engineering Quality Other	
Root	·				Descri	ption of work order update	Initi	ial	Action		Sign &			· · · · · · · · · · · · · · · · · · ·
Cause	\Box	Date	Step	Qty	(or Non-conformance	Chief	Eng	Description		Date	Verification	'n	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved					·									
							AULT C	ATE	GORY					
Landi	_	Bending Centre No Cracks Crushed/		ntric to	o/s	General Bend BOM/Route Broken/Damaged Burrs	Ha	•	re on Incomplete ions Incomplete/Unclear		Ovalized Over/Under Part Incorred Part Lost/Mi	et		Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled
	\vdash	Cuffs	cpcu			Contamination	-		nance	\Box	Part Moved	JJ116 .	Ш	THIONG STOCK I WHEN

Mislabeled

Out of Calibration

Out of Sequence

Outside Dimensions

Misread

Offset

Positioned Wrong

Power Loss/Surge

Other

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Heat Treat

Inspection Strip in Tube

Torque Waves in Extrusion

Countersink

Cut Too Short

Drill Holes

Drawing

Finish

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G


DART AEROSPACE LTD	Work Order:	108448
Description: Fuel Pick Up Line	Part Number:	D4003-5
Inspection Dwg: D4003 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.50	+/-0.030	.499	/		VERN	P40-12
90°	+/-0.5°	900	V		Ava G.	
45°	+/-0.5°	45°			. 4.	
0.035	+/-0.010	.034	~		VGRN	PL10-12
35.01	+/-0.030	35,01	/		M Tape	Pep-11
2.88	+/-0.030	2,910			VGAN'	P40-11 P40-12
2.78	+/-0.030	2.810	/		10	L.
0.19	+/-0.030	. 190	/		11	
Ø0.098	+0.004/-0.001	. 098	/		1,	, ,
0.34	+/-0.030	. 343			1.	
0.44	+/-0.030	.444			j.	1,
		·				
	LONG					

Measured by:	Audited by: A Preliminary Approval:	
Date: [3/11/02_	Date: 3 11 03 9-8 Date:	

Rev	Date	Change	Rev		y Approved
A	10.10.25	New Issue	KJ	W	A A
				77	



ITEM NO.	QTY. -049	PART NUMBER	DESCRIPTION -	JOHN CAMERON AVIATION PART NUMBER
1	X	D4003-049	TANK VENT LINE ASSEMBLY	JCA-M47-2-17
2	1	D4003-9	VENT LINE	
3	1	AN818-8D	NUT	
4	1	MS20819-8D	SLEEVE	



D4003-049 TANK VENT LINE ASSEMBLY

D

8

NOTES:
1) MATERIAL: N/A
2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: IDENTIFY WITH DART P/N "D4003-049" AND B/N USING FINE POINT PERMANENT INK MARKER
7) WEIGHT: 0.11 lbs

DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA DRAWN DRAWING NO. CHECKED REV. A D4003 MFG. APPR. SHEET 2 OF 9 APPROVED TITLE SCALE DE APPR. COPYRIGHT © 2010 BY DART AEROSPACE LTD

THE DOCUMENT IS PRIVITE AND COMPOSITIES OF THE COMPLETE CONTROL THE TITLE OF THE COMPLETE CONTROL THE TITLE OF THE COMPLETE CONTROL THE TITLE OF THE COMPLETE COM DATE 10.02.05

DESIGN

3

